

Support for Ethernet Switches

Part Number **NVIDIA Part Number** **Description**

Recommended Support by Ethernet Switch SN4000 Series Part Numbers

| | | |
|---------------|--------------------|-------------------------|
| SUP-SN4600-1S | 780-S46N0Z+P2CMI12 | 1 Year Standard Support |
| SUP-SN4600-2S | 780-S46N0Z+P2CMI24 | 2 Year Standard Support |
| SUP-SN4600-3S | 780-S46N0Z+P2CMI36 | 3 Year Standard Support |
| SUP-SN4600-4S | 780-S46N0Z+P2CMI48 | 4 Year Standard Support |
| SUP-SN4600-5S | 780-S46N0Z+P2CMI60 | 5 Year Standard Support |

Required Cumulus Support licences by Ethernet Switch SN4000 Series Part Numbers

| | | |
|------------------|--------------------|-------------------------|
| SUP-SN4600-CL-1S | 781-S46N0Z+P2CMI12 | 1 Year Standard Support |
| SUP-SN4600-CL-2S | 781-S46N0Z+P2CMI24 | 2 Year Standard Support |
| SUP-SN4600-CL-3S | 781-S46N0Z+P2CMI36 | 3 Year Standard Support |
| SUP-SN4600-CL-4S | 781-S46N0Z+P2CMI48 | 4 Year Standard Support |
| SUP-SN4600-CL-5S | 781-S46N0Z+P2CMI60 | 5 Year Standard Support |

Recommended Support by Ethernet Switch SN3000 Series Part Numbers

| | | |
|---------------|--------------------|-------------------------|
| SUP-SN3700-1S | 780-S37N0Z+P2CMI12 | 1 Year Standard Support |
| SUP-SN3700-2S | 780-S37N0Z+P2CMI24 | 2 Year Standard Support |
| SUP-SN3700-3S | 780-S37N0Z+P2CMI36 | 3 Year Standard Support |
| SUP-SN3700-4S | 780-S37N0Z+P2CMI48 | 4 Year Standard Support |
| SUP-SN3700-5S | 780-S37N0Z+P2CMI60 | 5 Year Standard Support |

Required Cumulus Support licences by Ethernet Switch SN3000 Series Part Numbers

| | | |
|------------------|--------------------|-------------------------|
| SUP-SN3700-CL-1S | 781-S37N0Z+P2CMI12 | 1 Year Standard Support |
| SUP-SN3700-CL-2S | 781-S37N0Z+P2CMI24 | 2 Year Standard Support |
| SUP-SN3700-CL-3S | 781-S37N0Z+P2CMI36 | 3 Year Standard Support |
| SUP-SN3700-CL-4S | 781-S37N0Z+P2CMI48 | 4 Year Standard Support |
| SUP-SN3700-CL-5S | 781-S37N0Z+P2CMI60 | 5 Year Standard Support |

For more information, contact a PNY account manager or email GOPNY@PNY.COM
WWW.PNY.COM/NETWORKING

Support for Ethernet Switches

Part Number NVIDIA Part Number Description

Recommended Support by Ethernet Switch SN2010 Part Numbers

| | | |
|---------------|--------------------|-------------------------|
| SUP-SN2010-1S | 780-S21N0Z+P2CMI12 | 1 Year Standard Support |
| SUP-SN2010-2S | 780-S21N0Z+P2CMI24 | 2 Year Standard Support |
| SUP-SN2010-3S | 780-S21N0Z+P2CMI36 | 3 Year Standard Support |
| SUP-SN2010-4S | 780-S21N0Z+P2CMI48 | 4 Year Standard Support |
| SUP-SN2010-5S | 780-S21N0Z+P2CMI60 | 5 Year Standard Support |

Required Cumulus Support licences by Ethernet Switch SN2010 Part Numbers

| | | |
|------------------|--------------------|-------------------------|
| SUP-SN2010-CL-1S | 781-S21N0Z+P2CMI12 | 1 Year Standard Support |
| SUP-SN2010-CL-2S | 781-S21N0Z+P2CMI24 | 2 Year Standard Support |
| SUP-SN2010-CL-3S | 781-S21N0Z+P2CMI36 | 3 Year Standard Support |
| SUP-SN2010-CL-4S | 781-S21N0Z+P2CMI48 | 4 Year Standard Support |
| SUP-SN2010-CL-5S | 781-S21N0Z+P2CMI60 | 5 Year Standard Support |

Required Cumulus Support licences by Ethernet Switch SN2100 Part Numbers

| | | |
|------------------|--------------------|-------------------------|
| SUP-SN2100-CL-1S | 781-S22N0Z+P2CMI12 | 1 Year Standard Support |
| SUP-SN2100-CL-2S | 781-S22N0Z+P2CMI24 | 2 Year Standard Support |
| SUP-SN2100-CL-3S | 781-S22N0Z+P2CMI36 | 3 Year Standard Support |
| SUP-SN2100-CL-4S | 781-S22N0Z+P2CMI48 | 4 Year Standard Support |
| SUP-SN2100-CL-5S | 781-S22N0Z+P2CMI60 | 5 Year Standard Support |

Required Cumulus Support licences by Ethernet Switch SN2410 Part Numbers

| | | |
|--------------------|--------------------|-------------------------|
| SUP-SN2000-CL-L-1S | 781-S24N0Z+P2CMI12 | 1 Year Standard Support |
| SUP-SN2000-CL-L-2S | 781-S24N0Z+P2CMI24 | 2 Year Standard Support |
| SUP-SN2000-CL-L-3S | 781-S24N0Z+P2CMI36 | 3 Year Standard Support |
| SUP-SN2000-CL-L-4S | 781-S24N0Z+P2CMI48 | 4 Year Standard Support |
| SUP-SN2000-CL-L-5S | 781-S24N0Z+P2CMI60 | 5 Year Standard Support |

For more information, contact a PNY account manager or email GOPNY@PNY.COM
WWW.PNY.COM/NETWORKING

Support for Ethernet and InfiniBand Switches

| Part Number | NVIDIA Part Number | Description |
|---|--------------------|--|
| Standalone Cumulus Software Licenses (Inquire for support on Cumulus) | | |
| UPGR-CUM2010 | 798-LCLU2Z+P2CMI00 | Cumulus Linux license for Mellanox SN2010 25G Ethernet half-width Switch. |
| UPGR-CUM-LRG_SPINE | 798-LCLLSZ+P2CMI00 | Cumulus Linux software license for 64x100GbE or 32x200GbE Large spine Ethernet Switch. |
| UPGR-CUM-SUPER_SPINE | 798-LCLSUZ+P2CMI00 | Cumulus Linux software license for 64x200GbE or 32x400GbE Super spine Ethernet Switch. |
| UPGR-CUM-SPINE | 798-LCLUSZ+P2CMI00 | Cumulus Linux software license for Mellanox 32x100GbE spine Ethernet Switches. |
| UPGR-CUM-LEAF | 798-LCLULZ+P2CMI00 | Cumulus Linux software license for Mellanox leaf Ethernet Switches. |
| UPGR-CUM2100-100G | 798-LCLUGZ+P2CMI00 | Cumulus Linux software license for Mellanox SN2100 Series 100G Ethernet Switch. |
| UPGR-CUM2100-40G | 798-LCLU4Z+P2CMI00 | Cumulus Linux software license for Mellanox SN2100 Series 40G Ethernet Switch. |
| NetQ Telemetry Software | | |
| UPGR-CUM-NETQ2-SUB-10G-1YR | 797-XNQ10Z+P2CMI12 | NETQ2-10G Subscription SW with Business Standard, 1 Year |
| UPGR-CUM-NETQ2-SUB-10G-3YR | 797-XNQ10Z+P2CMI36 | NETQ2-10G Subscription SW with Business Standard, 3 Years |
| UPGR-CUM-NETQ2-SUB-10G-5YR | 797-XNQ10Z+P2CMI60 | NETQ2-10G Subscription SW with Business Standard, 5 Years |
| Required Support InfiniBand CS8500 | | |
| SUP-CS8500-1S | 791-SH8N0Z+P2CMI12 | 1 Year Standard Support |
| SUP-CS8500-2S | 791-SH8N0Z+P2CMI24 | 2 Year Standard Support |
| SUP-CS8500-3S | 791-SH8N0Z+P2CMI36 | 3 Year Standard Support |
| SUP-CS8500-4S | 791-SH8N0Z+P2CMI48 | 4 Year Standard Support |
| SUP-CS8500-5S | 791-SH8N0Z+P2CMI60 | 5 Year Standard Support |
| Required Support InfiniBand CS7500 | | |
| SUP-CS7500-1S | 791-SE5N0Z+P2CMI12 | 1 Year Standard Support |
| SUP-CS7500-2S | 791-SE5N0Z+P2CMI24 | 2 Year Standard Support |
| SUP-CS7500-3S | 791-SE5N0Z+P2CMI36 | 3 Year Standard Support |
| SUP-CS7500-4S | 791-SE5N0Z+P2CMI48 | 4 Year Standard Support |
| SUP-CS7500-5S | 791-SE5N0Z+P2CMI60 | 5 Year Standard Support |

For more information, contact a PNY account manager or email GOPNY@PNY.COM
WWW.PNY.COM/NETWORKING

Support for InfiniBand Switches

| Part Number | NVIDIA Part Number | Description |
|---|--------------------|-------------------------|
| Required Support InfiniBand CS7520 | | |
| SUP-CS7520-1S | 791-SE2N0Z+P2CMI12 | 1 Year Standard Support |
| SUP-CS7520-2S | 791-SE2N0Z+P2CMI24 | 2 Year Standard Support |
| SUP-CS7520-3S | 791-SE2N0Z+P2CMI36 | 3 Year Standard Support |
| SUP-CS7520-4S | 791-SE2N0Z+P2CMI48 | 4 Year Standard Support |
| SUP-CS7520-5S | 791-SE2N0Z+P2CMI60 | 5 Year Standard Support |

| | | |
|---|--------------------|-------------------------|
| Required Support InfiniBand 8700 Series Quantum Switches | | |
| SUP-QM8700-1S | 790-SHQN0Z+P2CMI12 | 1 Year Standard Support |
| SUP-QM8700-2S | 790-SHQN0Z+P2CMI24 | 2 Year Standard Support |
| SUP-QM8700-3S | 790-SHQN0Z+P2CMI36 | 3 Year Standard Support |
| SUP-QM8700-4S | 790-SHQN0Z+P2CMI48 | 4 Year Standard Support |
| SUP-QM8700-5S | 790-SHQN0Z+P2CMI60 | 5 Year Standard Support |

| | | |
|---|--------------------|-------------------------|
| Required Support InfiniBand 7800 Series Switches | | |
| SUP-SB7800-1S | 790-SE0N0Z+P2CMI12 | 1 Year Standard Support |
| SUP-SB7800-2S | 790-SE0N0Z+P2CMI24 | 2 Year Standard Support |
| SUP-SB7800-3S | 790-SE0N0Z+P2CMI36 | 3 Year Standard Support |
| SUP-SB7800-4S | 790-SE0N0Z+P2CMI48 | 4 Year Standard Support |
| SUP-SB7800-5S | 790-SE0N0Z+P2CMI60 | 5 Year Standard Support |

| | | |
|---|--------------------|-------------------------|
| Required Support InfiniBand 7890 Series Switches | | |
| SUP-SB7890-1S | 790-SE0N0Z+P2CMI12 | 1 Year Standard Support |
| SUP-SB7890-2S | 790-SE0N0Z+P2CMI24 | 2 Year Standard Support |
| SUP-SB7890-3S | 790-SE0N0Z+P2CMI36 | 3 Year Standard Support |
| SUP-SB7890-4S | 790-SE0N0Z+P2CMI48 | 4 Year Standard Support |
| SUP-SB7890-5S | 790-SE0N0Z+P2CMI60 | 5 Year Standard Support |

For more information, contact a PNY account manager or email GOPNY@PNY.COM
WWW.PNY.COM/NETWORKING

Support for InfiniBand/BlueField/SmartNICs

| Part Number | NVIDIA Part Number | Description |
|---|--------------------|-------------------------|
| Required Support InfiniBand 7700 Series Routers | | |
| SUP-SB7700-1S | 790-SE7N0Z+P2CMI12 | 1 Year Standard Support |
| SUP-SB7700-2S | 790-SE7N0Z+P2CMI24 | 2 Year Standard Support |
| SUP-SB7700-3S | 790-SE7N0Z+P2CMI36 | 3 Year Standard Support |
| Recommended Support InfiniBand to Ethernet Gateways | | |
| SUP-SX6710G-1S | 790-S69N0Z+P2CMI12 | 1 Year Standard Support |
| SUP-SX6710G-2S | 790-S69N0Z+P2CMI24 | 2 Year Standard Support |
| SUP-SX6710G-3S | 790-S69N0Z+P2CMI36 | 3 Year Standard Support |
| SUP-SX6710G-4S | 790-S69N0Z+P2CMI48 | 4 Year Standard Support |
| SUP-SX6710G-5S | 790-S69N0Z+P2CMI60 | 5 Year Standard Support |
| Recommended Support for BlueField and BlueField-2 DPUs | | |
| SUP-ADPTR-BF-1S | 783-SBFN0Z+P2CMI12 | 1 Year Standard Support |
| SUP-ADPTR-BF-2S | 783-SBFN0Z+P2CMI24 | 2 Year Standard Support |
| SUP-ADPTR-BF-3S | 783-SBFN0Z+P2CMI36 | 3 Year Standard Support |
| SUP-ADPTR-BF-4S | 783-SBFN0Z+P2CMI48 | 4 Year Standard Support |
| SUP-ADPTR-BF-5S | 783-SBFN0Z+P2CMI60 | 5 Year Standard Support |
| Required Support for ConnectX-6 VPI SmartNIC Adapters | | |
| SUP-ADPTR-1S | 783-SADN0Z+P2CMI12 | 1 Year Standard Support |
| SUP-ADPTR-2S | 783-SADN0Z+P2CMI24 | 2 Year Standard Support |
| SUP-ADPTR-3S | 783-SADN0Z+P2CMI36 | 3 Year Standard Support |
| SUP-ADPTR-4S | 783-SADN0Z+P2CMI48 | 4 Year Standard Support |
| SUP-ADPTR-5S | 783-SADN0Z+P2CMI60 | 5 Year Standard Support |

For more information, contact a PNY account manager or email GOPNY@PNY.COM
WWW.PNY.COM/NETWORKING

Support for SmartNIC Adapters

| Part Number | NVIDIA Part Number | Description |
|--|--------------------|-------------------------|
| Recommended Support for ConnectX-5 Ethernet SmartNIC Adapters | | |
| SUP-ADPTR-ETH-1S | 783-SEAN0Z+P2CMI12 | 1 Year Standard Support |
| SUP-ADPTR-ETH-2S | 783-SEAN0Z+P2CMI24 | 2 Year Standard Support |
| SUP-ADPTR-ETH-3S | 783-SEAN0Z+P2CMI36 | 3 Year Standard Support |
| SUP-ADPTR-ETH-4S | 783-SEAN0Z+P2CMI48 | 4 Year Standard Support |
| SUP-ADPTR-ETH-5S | 783-SEAN0Z+P2CMI60 | 5 Year Standard Support |
| Recommended Support for ConnectX-5 InfiniBand SmartNIC Adapters | | |
| SUP-ADPTR-1S | 783-SADN0Z+P2CMI12 | 1 Year Standard Support |
| SUP-ADPTR-2S | 783-SADN0Z+P2CMI24 | 2 Year Standard Support |
| SUP-ADPTR-3S | 783-SADN0Z+P2CMI36 | 3 Year Standard Support |
| SUP-ADPTR-4S | 783-SADN0Z+P2CMI48 | 4 Year Standard Support |
| SUP-ADPTR-5S | 783-SADN0Z+P2CMI60 | 5 Year Standard Support |
| Recommended Support for ConnectX-4 Ethernet SmartNIC Adapters | | |
| SUP-ADPTR-ETH-1S | 783-SEAN0Z+P2CMI12 | 1 Year Standard Support |
| SUP-ADPTR-ETH-2S | 783-SEAN0Z+P2CMI24 | 2 Year Standard Support |
| SUP-ADPTR-ETH-3S | 783-SEAN0Z+P2CMI36 | 3 Year Standard Support |
| SUP-ADPTR-ETH-4S | 783-SEAN0Z+P2CMI48 | 4 Year Standard Support |
| SUP-ADPTR-ETH-5S | 783-SEAN0Z+P2CMI60 | 5 Year Standard Support |

For more information, contact a PNY account manager or email GOPNY@PNY.COM
WWW.PNY.COM/NETWORKING